

Double Lock EZr™ Gooseneck Hitches

Make / Model	Style	Years	Kit# (Hitch and Brackets)	Footnotes	Hitch#	Bracket#
Chevrolet						
Silverado 2500	Excluding Cab & Chassis	01 - 04	60681	Z	60619	60648
Silverado 2500 HD	6.75' bed	20 - 21	60687	Z	60611	60696
Silverado 2500 HD	Excluding Cab & Chassis	01 - 10	60681	Z	60619	60648
Silverado 2500 HD	Excluding Cab & Chassis	11 - 19	60680	1, Z	60611	60624
Silverado 2500 HD Classic	Excluding Cab & Chassis	07 - 07	60681	Z	60619	60648
Silverado 3500	Excluding Cab & Chassis	01 - 06	60681	Z	60619	60648
Silverado 3500 Classic	Excluding Cab & Chassis	07 - 07	60681	Z	60619	60648
Silverado 3500 HD	6.75' bed	20 - 21	60687	Z	60611	60696
Silverado 3500 HD	Excluding Cab & Chassis	07 - 10	60681	Z	60619	60648
Silverado 3500 HD	Excluding Cab & Chassis	11 - 19	60680	1, Z	60611	60624
Dodge						
Ram 2500	Excluding Cab & Chassis	03 - 10	60682	1, 2, 3, Z	60619	60660
Ram 3500	Excluding Cab & Chassis	03 - 10	60682	1, 2, 3, Z	60619	60660
Ford						
F-250	ALL	99 - 99	60685	Z	60619	60647
F-250 Super Duty	ALL	11 - 16	60683	Z	60619	60645
F-250 Super Duty	ALL	99 - 10	60685	Z	60619	60647
F-350 Super Duty	Excluding Cab & Chassis	11 - 16	60683	Z	60619	60645
F-350 Super Duty	Excluding Cab & Chassis	99 - 10	60685	Z	60619	60647
GMC						
Sierra 2500	Excluding Cab & Chassis	01 - 04	60681	Z	60619	60648
Sierra 2500 HD	6.75' bed	20 - 21	60687	Z	60611	60696
Sierra 2500 HD	Excluding Cab & Chassis	01 - 10	60681	Z	60619	60648
Sierra 2500 HD	Excluding Cab & Chassis	11 - 19	60680	1, Z	60611	60624
Sierra 2500 HD Classic	Excluding Cab & Chassis	07 - 07	60681	Z	60619	60648
Sierra 3500	Excluding Cab & Chassis	01 - 06	60681	Z	60619	60648
Sierra 3500 Classic	Excluding Cab & Chassis	07 - 07	60681	Z	60619	60648
Sierra 3500 HD	6.75' bed	20 - 21	60687	Z	60611	60696
Sierra 3500 HD	Excluding Cab & Chassis	07 - 10	60681	Z	60619	60648
Sierra 3500 HD	Excluding Cab & Chassis	11 - 19	60680	1, Z	60611	60624
Ram						
2500	ALL	11 - 13	60682	1, 2, 3, Z	60619	60660
3500	Excluding Cab & Chassis	11 - 12	60682	1, 2, 3, Z	60619	60660

Footnotes

- 1 - Passenger-side wheel well must be notched for frame rail access
- 2 - Parking brake cable bracket may require relocation
- 3 - Exhaust may have to be permanently lowered on 2005 and newer models
- 4 - Vacuum canister requires relocation (kit included)
- 5 - Ball cannot be turned over. Brake lines must be cable tied (ties included)
- 6 - Do not invert ball with heavy loads on two-wheel drive models
- Z - No frame drilling required

All Models: Brake, fuel, and electrical lines may need to be loosened or repositioned. Heat shield requires modification or removal.

*Continued while supplies last