

ZHS-137

16115 DISPLAY STAND

6/25/08

Parts List			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	3	1_2 - 13 x 3 CARRIAGE	CARRIAGE BOLT
2	7	HFN 1213	HEX FLANGE NUT
3	4	1/2-13 x 1 1/2	CARRIAGE BOLT
4	2	1_4 - 20 x 3_4 HEX	HEX BOLT

STEP 2:
- ATTACH SIGN HOLDER
- PLACE 16115 CROSS MEMBER WELDMENT ON OUTSIDE OF POST
- FINISH INSTALLING 16115
- TORQUE 1/2" FASTENERS TO 75 LB-FT.

CROSS MEMBER
(SOLD WITH 16115)

SIGN HOLDER

POST

FOOT

STEP 1:
- ASSEMBLE FOOT PIECES TO POST
- TORQUE 1/2" FASTENERS TO 75 LB-FT

