
1978-1996 JEEP CJ5 & CJ7

11/13/2020

GROSS LOAD CAPACITY WHEN USED AS A WEIGHT CARRYING HITCH: 4,000 LBS. TRAILER WEIGHT & 400 LBS. TONGUE WEIGHT.

DO NOT EXCEED VEHICLE MANUFACTURER'S RECOMMENDED TOWING CAPACITY.

Parts List			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	4	30-00133	WASHER,FLAT,1/2,YZ
2	2	20-00143	NUT,NYL LOCK,1/2-13 UNC,GRD8,YZ
3	2	10-10413	HHCS,1/2-13 UNC,4-1/2,GRD8,YZ
4	2	10-10478	HEX BOLT
5	8	10-10415	HHCS,7/16-14 UNC,1-1/2,GRD8,YZ
6	4	10-10497	HHCS,7/16-14 UNC,2,GRD8,YZ
7	22	30-00166	WASHER,FLAT,7/16,YZ
8	8	20-00142	NUT,NYL LOCK,7/16-14 UNC,GRD8,YZ
9	6	10-10479	HEX BOLT
10	4	CM-SP38	1/2" WEDGE SPACER
11	2	CM-SP22	.250 x 1.50 x 1.50" ROUND HOLE SPACER
12	2	CM-13412-SB	.250" SUPPORT BRACKET
13	2	CM-13412-WNP1	WELD NUT PLATE
14	2	CM-13412-WNP2	WELDNUT PLATE



INSTALLATION STEPS

- 1) Raise hitch into position against rear crossmember on your vehicle. Start a 7/16 x 1 1/2" bolt and part # CM-13412-WNP2 to inside holes each side of center section of hitch. (Note: Use 7/16 x 2" bolt when using special aftermarket bumper.)
- 2) Slide driver and passenger side arms into the hitch body and proceed to install hardware as shown.
- 3) A 1/2" hole will need to be drilled in the frame on each side to accommodate the 7/16 x 3 3/4" bolt and the part # CM-13412-WNP1. Use the hole in the side arm as a template.
- 4) Torque 7/16" fasteners to 70 lb.-ft. Torque 1/2" fasteners to 110 lb.-ft. Torque 5/8" fasteners to 50 lb.-ft.

PERIODICALLY CHECK THIS RECEIVER HITCH TO ENSURE THAT ALL FASTENERS ARE TIGHT AND THAT ALL STRUCTURAL COMPONENTS ARE SOUND.

Curt Manufacturing Inc., warrants this product to be free of defects in material and/or workmanship at the time of retail purchase by the original purchaser. If the product is found to be defective, Curt Manufacturing Inc., may repair or replace the product, at their option, when the product is returned, prepaid, with proof of purchase. Alteration to, misuse of, or improper installation of this product voids the warranty. Curt Manufacturing Inc.'s liability is limited to repair or replacement of products found to be defective, and specifically excludes liability for incidental or consequential loss or damage.